

UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 57503
CSAH NO. 7
OVER THE
RED LAKE RIVER
DISTRICT 2 - PENNINGTON COUNTY



PREPARED FOR THE
MINNESOTA DEPARTMENT OF TRANSPORTATION
BY
COLLINS ENGINEERS, INC.
JOB NO. 5221 (CEI 164)

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

REPORT SUMMARY:

The substructure units inspected at Bridge No. 57503, Piers 1 and 2, were found to be in good condition with no defects of structural significance observed. A moderate accumulation of timber debris extending from the channel bottom to the waterline was observed around the entire perimeter of Pier 1, extending up to 10 feet off the pier faces and noses. As noted in the previous inspection, a minor scour depression was observed at the upstream end of Pier 2. Overall, the channel bottom at the bridge appeared stable with no significant changes from the last inspection.

INSPECTION FINDINGS:


- (A) An 8-inch length of exposed reinforcing steel was observed at the waterline at the upstream end of Pier 1.
- (B) A minor scour depression, which was 3 feet in diameter and 1 foot deep, was observed at the upstream end of Pier 2.
- (C) A moderate accumulation of timber debris, which included drift up to 1 foot in diameter, was observed around the upstream nose from the channel bottom to the waterline and extending 10 feet off the faces and noses of Pier 1.

RECOMMENDATIONS:

- (A) Remove the timber debris from around Pier 1 to alleviate further accumulations, scour influence, and excessive lateral loads on the pier.
- (B) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.


Daniel G. Stromberg

A large, stylized handwritten signature in black ink, appearing to read 'Dan G. Stromberg', is written over two horizontal lines.

Date 6/30/2008 Registration No. 21491

Respectfully submitted,

COLLINS ENGINEERS, INC.

A large, stylized handwritten signature in black ink, appearing to read 'Dan G. Stromberg', is written over two horizontal lines.

Daniel G. Stromberg
Registered Professional
Engineer, State of Minnesota

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

1. BRIDGE DATA

Bridge Number: 57503

Feature Crossed: Red Lake River

Feature Carried: CSAH No. 7

Location: District 2 - Pennington County

Bridge Description: The bridge superstructure consists of three spans of multiple steel beams supporting a reinforced concrete deck. The superstructure is supported by two reinforced concrete abutments and two reinforced concrete piers. The piers are numbered starting from the west end of the bridge. No design drawings were provided.

2. INSPECTION DATA

Professional Engineer Diver: Bradley A. Syler, P.E., S.E.

Dive Team: John J. Loftus, Valerie Roustan

Date: August 18, 2007

Weather Conditions: Sunny, 69°F

Underwater Visibility: 4.0 feet

Waterway Velocity: 1.0 f.p.s.

3. SUBSTRUCTURE INSPECTION DATA

Substructure Inspected: Piers 1 and 2.

General Shape: The piers each consist of a rectangular reinforced concrete shaft with rounded ends. They support a rectangular reinforced concrete hammerhead pier cap with tapered ends.

Maximum Water Depth at Substructure Inspected: Approximately 5.4 feet.

4. WATERLINE DATUM

Water Level Reference: The top of the pier cap on the north end of Pier 2.

Water Surface: The waterline was approximately 11.0 feet below reference.
Assumed Waterline Elevation = 89.0.

5. NBIS CODING INFORMATION (Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code 7

Item 61: Channel and Channel Protection: Code 6

Item 92B: Underwater Inspection: Code B/08/07

Item 113: Scour Critical Bridges: Code I/94

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

 Yes X No




Photograph 1. Overall View of the Structure, Looking North.



Photograph 2. View of Pier 1, Looking East.



Photograph 3. View of Pier 2, Looking Northwest.



SOUNDING PLAN

GENERAL NOTES:

1. Piers 1 and 2 were inspected at this bridge.
2. At the time of inspection on August 18, 2007, the waterline was located approximately 11.0 feet below the top of the pier cap on the downstream end of Pier 2. Design plans were not available, therefore a reference of 100.0 was assumed. Based on the assumed reference the waterline elevation was 89.0.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken parallel to the bridge at 1/4 point intervals between the substructure units as well as around the pier structures.

INSPECTION NOTES:

- 1 Overall, the concrete piers were smooth and sound with an 8-inch length of exposed reinforcing steel located at the waterline at the upstream end of Pier 1. In addition, minor scaling was observed at the upstream nose of Piers 1 and 2 from channel bottom to 4 feet above the waterline.
- 2 A minor scour depression, 1 foot deep with a radius of 3 feet, was observed at the upstream end of Pier 2.
- 3 A moderate accumulation of timber debris, which included drift up to 1 foot in diameter, was observed around the entire perimeter of Pier 1 from the channel bottom to the waterline and up to 10 feet off the pier faces and noses.
- 4 The channel bottom around the entire perimeters of Piers 1 and 2 consisted of sand and gravel and random rip rap up to 1 foot in diameter with up to 6 inches of probe rod penetration.

Legend

- 6.0 Sounding Depth (8/18/07)
- 6.5 Sounding Depth (8/27/02)
- Timber Debris
- Scour Depression

Note:

All soundings based on 2007 waterline location.


**MINNESOTA
DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION**

STRUCTURE NO. 57503
OVER THE RED LAKE RIVER
DISTRICT 2, PENNINGTON COUNTY


INSPECTION AND SOUNDING PLAN

Drawn By: PRH	COLLINS ENGINEERS 123 North Wacker Drive Suite 300 Chicago, IL 60606 (312) 704-9300 www.collinsengr.com	Date: AUGUST, 2007
Checked By: MDK		Scale: NTS
Code: 52210164		Figure No.: 1

TYPICAL END VIEW OF PIERS



UPSTREAM FASCIA PROFILE
Vertical Scale: 1"=10'-0"



DOWNSTREAM FASCIA PROFILE
Vertical Scale: 1"=10'-0"

Note:
Refer to Figure 1 for General Notes.

**MINNESOTA
DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION**

STRUCTURE NO. 57503
OVER THE RED LAKE RIVER
DISTRICT 2, PENNINGTON COUNTY
**UPSTREAM AND DOWNSTREAM
FASCIA PROFILES**

Drawn By: PRH	COLLINS <small>123 North Wacker Drive Suite 300 Chicago, IL 60606 (312) 704-9300 www.collinsengr.com</small>	Date: AUGUST, 2007
Checked By: MDK		Scale: NTS (U.O.N.)
Code: 52210164		Figure No.: 2

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES
DAILY DIVING REPORT

INSPECTORS: Collins Engineers, Inc. DATE: August 18, 2007

ON-SITE TEAM LEADER: Bradley A. Syler, P.E., S.E.

BRIDGE NO: 57503 WEATHER: Sunny, 69°F

WATERWAY CROSSED: Red Lake River

DIVING OPERATION: X SCUBA SURFACE SUPPLIED AIR
 OTHER

PERSONNEL: John J. Loftus, Valerie Roustan

EQUIPMENT: Scuba, Probe Rod, Lead Line, Sounding Pole, U/W Light, Scraper, Camera

TIME IN WATER: 12:00 p.m.

TIME OUT OF WATER: 12:37 p.m.

WATERWAY DATA: VELOCITY 1.0 f.p.s.

VISIBILITY 4.0 feet

DEPTH 5.4 feet maximum at Pier 2

ELEMENTS INSPECTED: Piers 1 and 2

REMARKS: Overall, the concrete piers were generally smooth and sound with only an 8 inch length of exposed reinforced steel located at the waterline at the upstream end of Pier 1. In addition, minor scaling was observed at the upstream nose of Piers 1 and 2 from the channel bottom to 4 feet above the waterline. A minor scour depression was observed at the upstream end of Pier 2. A moderate accumulation of timber debris, which included drift up to 1 foot in diameter, was observed around the entire perimeter of Pier 1 from the channel bottom to the waterline extending up to 10 feet off the pier faces and noses.

FURTHER ACTION NEEDED: X YES NO

Remove the timber debris from around Pier 1 to alleviate further accumulations, scour influence, and excessive lateral loading on the pier.

Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES

UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 57503
INSPECTORS Collins Engineers, Inc.
ON-SITE TEAM LEADER Bradley A. Syler, P.E., S.E.
WATERWAY CROSSED Red Lake River

INSPECTION DATE August 18, 2007

NOTE: USE ALL APPLICABLE CONDITION DEFINITIONS AS DEFINED IN THE MINNESOTA RECORDING AND CODING GUIDE INCLUDING GENERAL, SUBSTRUCTURE, CHANNEL AND PROTECTION, AND CULVERTS AND WALL DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	SUBSTRUCTURE						CHANNEL					GENERAL					
			PILING	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	Pier 1	5.4'	N	7	N	9	N	7	7	7	7	5	6	7	N	N	N	N	N
	Pier 2	5.2'	N	7	N	9	N	7	7	7	7	N	7	7	N	N	N	N	N

*UNDERWATER PORTION ONLY

REMARKS: Overall, the concrete piers were generally smooth and sound with only an 8 inch length of exposed reinforced steel located at the waterline at the upstream end of Pier 1. In addition, minor scaling was observed at the upstream nose of Piers 1 and 2 from the channel bottom to 4 feet above the waterline. A minor scour depression was observed at the upstream end of Pier 2. A moderate accumulation of timber debris, which included drift up to 1 foot in diameter, was observed around the entire perimeter of Pier 1 from the channel bottom to the waterline extending up to 10 feet off the pier faces and noses.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO. USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.